


Accessories



Competence connects.



Accessories

Round brush



- 16805 Round brush for cleaning welding nozzles suitable for nozzles with Ø 4 and Ø 5 mm
- 24880 Round brush for cleaning welding nozzles suitable for nozzles with Ø 3 and Ø 4 mm

Adapter for hot air welding torches



- 22662 Adapter for hot air welding torches female thread M10, male thread M14

Adapter for Airtherm




- 19504 Adapter for Airtherm, thread M10
- 19503 Adapter for Airtherm, thread M14

Stanley knife



- 12344 Stanley knife Fat Max Extreme with retractable blade
- 23785 Knife holster for Fat Max Extreme
- 23786 Lutz spare blade for Fat Max Extreme (Pull Box with 10 blades)

Proof cutter



- 11221 Proof cutter, 20 mm, as per DVS 2225 part 4
- 11210 Proof cutter, 25 mm

Air flow meter




- 11087 Air flow meter
Pmax= 6,8 bar / 100 PSI 10 - 100 l/min
- 13125 Air flow meter for extruder
Pmax= 6,8 bar / 100 PSI 80 - 600 l/min

Temperature gauge



- 44011 Temperature measuring instrument for TC Type K with App connection
- 44012 Fast-action surface probe (TC type K) with fixed cable 1.2 m
- 44013 Fast-action immersion/penetration probe (TC type K) with fixed cable 1.2 m

WEG-Light



- 32478 WEG-Light for Duratherm, Duratherm2, Duratherm SC, Duratherm2 SC2, Autotherm2, Autotherm3, Exotherm (Hot gas welding torch is not included)

Quarter Moon Knife



- 10593 Quarter Moon Knife

Back-up roller



- 16406 Back-up roller

Draw Blade



- 18609 DE/EU
- 19046 US

Bead removing tool



- 44303 Bead removing tool
- 10814 Blade for Bead removing tool

Edge planer



- 44909 Edge planer with blade

Triangular scraper



- 22315 Triangular scraper
- 22314 Blade for scraper

Multi outline scraper



- 25218 Multi outline scraper
- 25216 Blade for scraper